


Soil Limitations for Development

The soil in Worthington is generally not conducive for development. *The Soil Survey of Hampden and Hampshire Counties, Western Part, Massachusetts*, published by the Natural Resources Conservation Service, states that every soil type in Worthington has severe limitations for septic tank absorption fields, mostly due to wetness and slope.



- Wetland soils**
 These soils are saturated or are under water.

- Steeply sloped soils**
 Soils that have a slope of 25 % or greater.

Worthington, Massachusetts 2006 Open Space and Recreation Plan Update

Conway School of Landscape Design

John Bisbing - Janna Thompson - Ian Warner

March 2006

Note: This map is intended for planning purposes only.

0 1 2 Miles

Sources: Worthington Community Development Plan, MassGIS, Pioneer Valley Planning Commission

- Rivers
- Roads
- Town Boundary